


➔ Suitable clothing

A visit to the factory premises requires some basic precautions. Unlike service providers, no special safety clothing is required for visitors, but you should wear sturdy, closed shoes and body-covering clothing (long sleeves, long trousers). Persons supervising the destruction of particular wastes due to legal requirements have to supply their own protective clothing: Flame-retarding jacket and trousers as well as safety footwear (at least S2 standard). GSB will provide protective helmet and safety goggles, if necessary.

➔ Rules of conduct

- Be sure to use the safety helmet and the integrated safety goggles.
- Follow the instructions of our staff and only stay in the area of the facility assigned to you or do not move away from the group of visitors.
- Smoking, eating, drinking and snuffing is only allowed in designated areas.
- Pay attention to the traffic inside the factory.
- The maximum permitted speed on the factory premises is 10 km/h.
- Please note the special dangers in the bunker area of the incinerator (danger of falling).
- Never touch or operate machines, equipment, containers, waste materials or chemicals.
- Trained first aiders and first aid kits are available in our company.
- All fire extinguishers and safety equipment are labelled and operated by our trained staff when needed.
- Major incidents are communicated via loudspeakers.
- Do not use any electronic devices such as cameras, mobile phones, etc. on the factory premises.

Directions



GSB Sonderabfall-Entsorgung Bayern GmbH

Äußerer Ring 50
85107 Baar-Ebenhausen

Tel. +49 8453 91-0
kontakt@gsb.bayern

www.gsb.bayern

Information for visitors and service providers

- Security instructions
- Access authorizations
- Rules of conduct
- Site plan and assembly points

Dear visitors and service providers,

We are very pleased to welcome you to the headquarters of GSB Sonderabfall-Entsorgung-Bayern GmbH.

Our company is represented throughout the Free State with a total of twelve operating locations and collection points.

At the 18-hectare Baar-Ebenhausen site, GSB operates two rotary kilns which, with a throughput capacity of 100,000 t / year each, represent the most powerful hazardous waste incineration plants in Central Europe. Together with the chemical-physical treatment plants and other facilities for acceptance, storage, pre-treatment, treatment and landfilling, we dispose of approx. 350,000 t of hazardous waste from industry, commerce and municipalities every year.


This leaflet is for your safety!

Please read it carefully and adhere to the following instructions and rules of conduct. If you have any questions, please contact our staff.

We wish you a pleasant stay on our factory premises!

➔ Access authorisation

Please wear your visitor's badge clearly visible on your body and report to the reception before leaving the factory premises. Please place the entry permit of your vehicle visible from the outside behind the windscreen. Please be sure to observe the signs in the entrance areas. In addition, as an external company employee, please observe instruction sheet D22001 and as a delivery driver or short-term supplier instruction sheet D22009, which you will receive from the GSB employee in charge (D22001) or from the employees of the scale (D22009).



Siren signals



Rising & falling tone:
Evacuation alarm, go to assembly points



Continuous tone, 2x interrupted:
Fire alarm, wait for announcements



Continuous tone:
All clear

Site plan legend

- | | |
|-------------------------------|-----------------------|
| Incinerators | Plant fire department |
| Chemical-physical treatment | Workshops |
| Biological treatment | Operating building |
| Warehouse and logistics areas | |

Signs explained

- Fire, naked lights and smoking prohibited; designated smoking areas excluded.
- Eating, drinking and snuffing forbidden; no alcohol allowed on the entire factory premises
- Operation of cell phones prohibited
- Photography and filming prohibited
- Specially marked areas: Prohibited for persons with pacemakers
- Warning of highly flammable or extremely flammable hazardous substances
- Warning against toxic hazardous substances
- Warning against corrosive hazardous substances
- Hard hat requirement
- Eye protection requirement
- Warning of explosive atmosphere; Non-explosion-proof electronic devices are prohibited
- When using GSB internal landline telephones: Emergency call of the Plant fire department
- Escape and rescue route
- Assembly point