
#### Suiteable clothing

A visit to the factory premises requires some basic precautions. Unlike service providers, no special safety clothing is required for visitors, but you should wear sturdy, closed shoes and body-covering clothing (long sleeves, long trousers). We will of course be happy to lend you the obligatory helmet with integrated safety goggles.

#### Rules of conduct

- Be sure to use the safety helmet and the integrated safety goggles.
- Follow the instructions of our staff and only stay in the area of the facility assigned to you or do not move away from the group of visitors.
- Smoking, eating, drinking and snuffing is only allowed in designated areas.
- Pay attention to the traffic inside the factory.
- The maximum permitted speed on the factory premises is 10 km/h.
- Please note the special dangers in the bunker area of the incinerator (danger of falling).
- Never touch or operate machines, equipment, containers, waste materials or chemicals.
- Trained first aiders and first aid kits are available in our company.
- All fire extinguishers and safety equipment are labelled and operated by our trained staff when needed.
- Major incidents are communicated via loudspeakers.
- Do not use any electronic devices such as cameras, mobile phones, etc. on the factory premises.

#### **Directions**



## and service providers

- Security instructions
- Site plan and assembly points

#### GSB Sonderabfall-Entsorgung Bayern GmbH

Äußerer Ring 50 85107 Baar-Ebenhausen

Tel. +49 8453 91-0 kontakt@gsb.bayern

www.gsb.bayern



# **Information for visitors**

- Access authorizations
- Rules of conduct

#### Dear visitors and service providers,

We are very pleased to welcome you to the headquarters of GSB Sonderabfall-Entsorgung-Bayern GmbH.

Our company is represented throughout the Free State with a total of twelve operating locations and collection points.

At the 18-hectare Baar-Ebenhausen site, GSB operates two rotary kilns which, with a throughput capacity of 100,000 t / year each, represent the most powerful hazardous waste incineration plants in Central Europe. Together with the chemical-physical treatment plants and other facilities for acceptance, storage, pre-treatment, treatment and landfilling, we dispose of approx. 350,000 t of hazardous waste from industry, commerce and municipalities every year.


#### This leaflet is for your safety!

Please read it carefully and adhere to the following instructions and rules of conduct. If you have any questions, please contact our staff.


We wish you a pleasant stay on our factory premises!

#### Access authorisation

Please wear your visitor's badge clearly visible on your body and report to the reception before leaving the factory premises. Please place the entry permit of your vehicle visible from the outside behind the windscreen. Please be sure to observe the signs in the entrance areas. In addition, as an external company employee, please observe instruction sheet D22001 and as a delivery driver or short-term supplier instruction sheet D22009, which you will receive from the GSB employee in charge (D22001) or from the employees of the scale (D22009).



#### Siren signals



### Rising & falling tone:

Evacuation alarm, go to assembly points

#### Continuous tone, 2x interrupted:

Fire alarm, wait for announcements

#### **Continuous tone:**

All clear

#### Site plan legend

Incinerators Plant fire department
Chemical-physical treatment Workshops
Biological treatment Operating building
Warehouse and logistics areas

#### Signs explained



Fire, naked lights and smoking prohibited; designated smoking areas excluded.



Eating, drinking and snuffing forbidden; no alcohol allowed on the entire factory premises



Operation of cell phones prohibited



Photography and filming prohibited



Specially marked areas: Prohibited for persons with pacemakers



Warning of highly flammable or extremely flammable hazardous substances



Warning against toxic hazardous substances



Warning against corrosive hazardous substances



Hard hat requirement



Eye protection requirement



Warning of explosive atmosphere; Non-explosion-proof electronic devices are prohibited



When using GSB internal landline telephones: Emergency call of the Plant fire department



Escape and rescue route



Assembly point